

# Operating Experience Alert

## Stop Use/Recall Notice

### 3M DBI-SALA® Shock Wave™ 2 Lanyards



Critical Risk Area

**What You Should Know:** 3M Fall Protection is issuing a Stop Use/Recall notice for select 3M DBI-SALA® ShockWave™ 2 Arc Flash shock absorbing lanyards (Figure 1). During an internal review, 3M Fall Protection identified a potential manufacturing issue with a limited number of devices (Table 1). This manufacturing issue could result in the lanyard not performing properly in the event of a fall, which could result in severe injury or death.



Figure 1. Recalled Lanyards

#### What You Can Do:

- Immediately check all shock absorbing lanyards in use and in inventory to determine if they are included in the list of recalled devices.
- Inspect the label on the lanyard (Figure 2) to determine the model number and manufacture date. Compare this information to the lanyards included in this recall (Table 1). **Note:** This recall covers all listed lanyards manufactured prior to June 2022.
- Immediately remove all lanyards included in the Stop Use & Recall Notice and return to Supply Chain for replacement.
- Follow the link to see the full text of the [3M® DBI-SALA™ ShockWave2 Arc Flash Shock Absorbing Lanyard](#) recall notice.





Figure 2. CSA Label (top) and ANSI Label (bottom)

Model Number				Description	Leg Style
3M® DBI SALA™ ShockWave2 Arc Flash Shock Absorbing . . .					
1224610	1224612	1224613	1244610	. . . Lanyard	Single Leg
1244612	1244613	1244615	1244618		
1224610B	1244610C	1244637C			
1224611	1244611	1244614	1244616	. . . Lanyard, Choker	
1244617	1244611B	1244611C			
1224630	1224632	1224633	1244630	. . . 100% Tie-Off Lanyard	Twin Leg
1244632	1244633	1244636	1244639		
1244630C	1244632B	1244630C	1244641C		
1224631	1224634	1244631	1244634	. . . 100% Tie-Off Lanyard, Choker	
1244635	1244638	1244631B	1244634B		
1244631C	1244638C	1244640C			

Table 1. Affected Lanyards

Contact Supply Chain or your local Health & Safety representative for assistance in the replacement of the recalled lanyards.