

Operating Experience Alert

Stop Use Notice – Crosby 7/8-in. 6.5t Shackle



Critical Risk Area

What You Should Know: The Crosby group, a rigging, lifting, and material-handling applications manufacturer, has determined that certain 6xWLL models (listed below) of their 7/8-in. screw pin anchor shackles may have a condition that reduces the ultimate load capacity below their listed catalogue values. The impacted shackles were shipped this year between May 10 and June 1. Continued use of these shackles may result in loss of load, leading to property damage or a potential serious injury or fatality. Crosby has issued an IMPORTANT SAFETY NOTICE for the following anchor shackles:

Recalled Part	Recalled Part Description
1019542	7/8-in. 6.50t S-2130 Shackle
1019533	7/8-in. 6.50t G-2130 Shackle
1018151	7/8-in. 6.50t G-213 Shackle
1018160	7/8-in. 6.50t S-213 Shackle
1018516	7/8-in. 6.50t G-209 Shackle
1018525	7/8-in. 6.50t S-209 Shackle



Figure 1. Recalled 7/8-in. shackle
Photo: Crosby

Note: A similar recall was issued for a  [1-in. Crosby shackle](#) on March 8, 2022.

What You Can Do:

- Immediately check all Crosby 7/8-in. anchor shackles in use or in inventory to determine if they are included in the list of affected products. The product identification code 5YH (circled in Figure 1) will be visible on all shackles included in this product recall.
- Immediately remove all shackles listed in the safety notice from service for return to your Crosby distributor for replacement. Work with your local Supply Chain representative to coordinate the return and replacement of Crosby anchor shackles.
- Use [this link](#) to reference the full text of the Crosby recall notice, which includes instructions for the return and replacement of the affected shackles.

Contact Supply Chain or your Local Safety Representative for assistance in replacement of the Crosby shackles listed in this alert.